

ABSTRACT

An insulative material is applied to one or more selected probe tips to disable those probes, and the probes are brought into contact with a semiconductor die. One or more tests are run on the die to verify sufficient testing of the die without the disabled probes. The process may be repeated with other probes disabled to determine which probes need not be used in testing the die.